

652 Oliver Street
Williamsport, PA. 17701 U.S.A.

Tel. 570-323-6181
Fax. 570-327-7101
www.lycoming.textron.com

SERVICE LETTER

Service Letter No. L114AN
(Supersedes Service Letter No. L114AM)
February 3, 2006

TO: Owners and Operators of Lycoming Aircraft Engines

SUBJECT: Reciprocating Engine and Accessory Maintenance Publications

NOTE

All publications may be ordered through authorized Lycoming distributors, or direct from Lycoming. **Payment must be remitted in U.S. dollars when ordering directly from the factory.**

The available maintenance publications for Lycoming engines and accessories consist of the following. **NOTE: Parts Catalogs will no longer be shipped with separate binders, but will be drilled. Binders can be purchased separately for \$8.00.**

ENGINE SPECIFICATIONS – Engine specifications may be purchased for a list price of \$10.00. Complete engine model information must be supplied when ordering. NOTE: Installation drawings are not included with engine specifications but can be purchased separately.

INSTALLATION DRAWINGS – Installation drawings may be purchased for a list price of \$40.00. Complete engine model information must be supplied when ordering.

OPERATOR'S MANUALS – The Operator's Manual contains information of use to pilots and maintenance personnel. It contains engine specifications, inspection procedures, and operational information and is used in conjunction with the aircraft owner's manual. **NOTE: All current revisions are included with Operator's Manuals.**

Part Number	Engine Application	Current Edition	Latest Revision	List Price
60297-3	O-340-A1A Engines	June 1975	----	\$20.00
60297-8	VO-435, TVO-435 Series	May 1976	60297-8-1	20.00
60297-9	O-235; O-290 Series	Jan. 1988	----	20.00
60297-10	O-540, IO-540 Series	March 1991	60297-10-5	20.00
60297-11	VO-360, IVO-360 Series	Dec. 1999	----	20.00
60297-12	O, HO, IO, LO, AIO, HIO, TIO-360 Series	Oct. 2005	----	20.00
60297-13	TIO-541 Series	June 1973	60297-13-2	20.00
60297-14●	GO-480, GSO-480, IGO-480, IGSO-480 Series	Oct. 1991	----	20.00
60297-15	IGO-540, IGSO-540 Series	July 1974	60297-15-1	20.00
60297-16	O-320, IO-320, AIO-320, LIO-320 Series	March 1973	60297-16-4	20.00
60297-17	VO-540, IVO-540, TIVO-540 Series	Dec. 1978	----	20.00
60297-19	IO-720 Series	Jan. 1988	----	20.00
60297-20	TO-360 Series	Feb. 1976	60297-20-3	20.00
60297-21	AEIO-320, -360 and -540 Series	Oct. 1974	60297-21-8	20.00
60297-22	O-320-H "76" Series	May 1976	60297-22-1	20.00
60297-23	TIO-540, LTIO-540 Series	March 1987	60297-23-10	20.00
60297-25	O-360-E, LO-360-E1A6D "76" Series	May 1978	60297-25-1	20.00
60297-26	TO-360-E, LTO-360 "76" Series	Oct. 1980	----	20.00
60297-27	TIO-540-AE2A Engines	Sept. 1988	60297-27-2	20.00
60297-28	IO-580-B1A (Operation and Installation)	April 2003		20.00
SSP1570	TIGO-541-E1A Engines	Nov. 1988	----	20.00

● - Photocopy.

OPERATOR'S MANUAL REVISIONS – Operator's manual revisions may be purchased for a list price of \$10.00 each. Complete engine model information must be supplied when ordering.

OVERHAUL MANUALS – The Overhaul Manual is a guide for major repair of the engine. It contains complete disassembly, inspection, repair, reassembly and test procedures for the various Lycoming reciprocating engines. When used in conjunction with the applicable parts catalog and service bulletins, service instructions and service letters; this manual provides an authoritative text for complete overhaul of the engine. Overhaul Manuals for current Lycoming engines are published in loose-leaf format to permit addition of revised or additional information without disturbing the unaffected portions. Each manual contains a registration card which, when properly executed and returned to Lycoming, assures that the owner will receive any additions or revisions that are made to the manual and Table of Limits, SSP-1776 within a specified time. Therefore, it is essential that Overhaul Manual owners return their registration cards. **NOTE: All current revisions are included with Overhaul Manuals.**

Part Number	Engine Application	Current Edition	Latest Revision	List Price
60294-5	Geared and Geared Supercharged Models	April 1970	60294-5-6	\$65.00
60294-6	Integral Accessory Drive Models	Oct. 1975	60294-6-3	65.00
60294-7	Direct Drive Models	Dec. 1974	60294-7-9	65.00
60294-8	Vertical Helicopter Models	April 1978	60294-8-3	65.00
60294-9	"76" Series Models	Aug. 1980	60294-9-2	65.00

OVERHAUL MANUAL REVISIONS – Overhaul Manual revisions may be purchased for a list price of \$15.00 each.

PARTS CATALOGS – Lycoming Parts Catalogs are illustrated to permit identification of parts; they are kept up to date by revision and supplemental listings. A referenced numerical index is also included. Price includes latest published supplements. Parts catalogs indicated by ♦ are currently only available as photocopies which may be purchased for one-half the list price. Complete engine serial numbers must be supplied with Parts Catalog orders. **NOTE: All current revisions are included with Parts Catalogs.**

Part Number	Engine Application	Cyl. Flange	Current Revision	Revision Number*	Revision Date	List Price
PC-102-1	O-290-D,-D2,-D2B,-D2C Engines		Jan. 1988	PC-102-1B♦	May 1991	\$30.00
PC-103	O-320-A2A,-A2B,-A2C,-A3A,-A3B,-A3C,-B2A,-B2B,-B3A,-B3B,-B3C,-D1A,-D1F,-D2A,-D2B,-D2C,-E1A,-E1F,-E2A,-E2B,-E2C,-E2D,-E2G,-E3D,; IO-320-B1A,-B1C,-C1A,-D1A,-D1B,-E2A; AIO-320-E1B,-E2B; LIO-320-B1A,-C1A	Std.	April 1970	SSP488	Aug. 1988	30.00
PC-105♦	O-340 Series		Feb. 1970			25.00
PC-106♦	O-360-A1A,-A2A,-A3A,-A1C,-A1D,-A2D,-A2E,-B2A,-C2A,-C2C,-C2D,-D2A,-D2B; IO-360-A1A,-B1A,-B1B; HO-360-B1A,-B1B; HIO-360-A1A,-B1A	Std.	April 1985			35.00
PC-107	VO & IVO-360		July 1963			20.00
PC-110	VO & TVO-435		Feb. 1963	SSP3071 SSP3071-1	Jan. 1972 Oct. 1972	30.00
PC-111♦	GO-480-B,-B1A6,-B1B,-B1C,-B1D,-D1A,-F6,-F1A6,-F2A6,-F4A6		Feb. 1969			30.00
PC-114♦	GSO & IGSO-480 Series		Oct. 1968	PC-114-1 SSP2471 PC-114-2 SSP780	Mar. 1970 Nov. 1971 Mar. 1974 Oct. 1980	30.00

♦ - Reprinted

• - Photocopy

Part Number	Engine Application	Cyl. Flange	Current Edition	Revision Number*	Revision Date	List Price
PC-115-1	O-540-A1A,-A1A5,-A1B5,-A1C5,-A1D,-A1D5,-A2B,-A3D5	Std.	March 1991	PC-115-1A	Oct. 1991	\$35.00
PC-115-2	O-540-B1A5,-B1B5,-B2B5,-B2C5,-B4B5,-E4A5,-E4B5,-E4C5,-G1A5,-G2A5	Std.	Feb. 1991	PC-115-2A	Oct. 1991	35.00
PC-116	IGO & IGSO-540 Series		June 1981			35.00
PC-118	VO & TIVO-540 Series		Feb. 1970	SSP1473	Nov. 1973	30.00
PC-119	IO-720-A1A,-A1B,-B1B,-B1BD,-C1B,-D1B	Std. & Wide	Nov. 1977	SSP778 PC-119-A	May 1978 Jan. 1983	30.00
PC-119-1	IO-720-D1C	Wide	Oct. 1982			15.00
PC-120	TIO-541 Series		Sept. 1974	PC-120-1	Jan. 1982	30.00
PC-121♦	TIGO-541 Series		Nov. 1975	PC-121-1 SSP1177	Sept. 1976 Dec. 1977	30.00
PC-122	O-320-H "76" Series		April 1976	PC-122-1	Dec. 1980	25.00
PC-123♦	O & LO-360-E1A6D "76" Series		July 1978			30.00
PC-124	TO & LTO-360 "76" Series		Dec. 1980	PC-124-1	May 1985	30.00
PC-203-1	O-320-A2B,-A2C,-A2D,-A3B,-E1A,-E1F,-E2A,-E2B,-E2C,-E2D,-E2F,-E2G,-E2H,-E3D,-E3H	Wide	July 1984			30.00
PC-203-2	O-320-B2B,-B2C,-B3B,-D1A,-D1D,-D1F,-D2A,-D2B,-D2C,-D2G,-D2J,-D3G	Wide	July 1984	PC-203-2A	Dec. 1985	30.00
PC-215-1	IO-540-A1A5,-B1A5,-B1C5,-C1B5,-C4B5,-C4C5,-D4A5,-E1A5,-E1B5,-G1A5,-G1B5,-G1C5,-G1D5,-G1E5,-G1F5	Std.	June 1993			35.00
PC-215-2	IO-540-J4A5,-K1A5,-K1B5,-K1C5,-K1D5,-K1E5,-K1F5,-M1A5,-N1A5,-P1A5,-R1A5,-S1A5	Std.	June 1993	SSP593	June 1993	35.00
PC-302	O-235-C1,-C1B,-C1C,-C2A,-C2C,-F2A,-F2B,-H2C,-J2A,-K2A,-K2B,-K2C,-L2A,-L2C,-M1,-N2A,-N2C		June 1982	PC-302A PC-302B	Feb. 1984 Jan. 1987	30.00
PC-302-1	O-235-P2A		Aug. 1985			15.00
PC-303	IO-320-B1A,-B1C,-C1A,-D1A,-D1B,-E1A,-E1B,-E2A,-E2B; AIO-320-B1B,-C1B; LIO-320-B1A,-C1A; AEIO-320-D1B,-D2B,-E1A,-E2A,-E1B,-E2B	Wide	June 1976	SSP1184-1	Jan. 1985	30.00
PC-306-1	O-360-A1A,-A1AD,-A1D,-A1F6,-A1F6D,-A1G6,-A1G6D,-A1LD,-A2A,-A2D,-A2F,-A2G,-A3A,-A3AD,-A4A,-A4G,-A4J,-A4K,-A4M,-A5AD	Wide	July 1980	PC-306-1A PC-306-1B	Mar. 1981 Nov. 1981	30.00
PC-306-2	O-360-B2A,-C1A,-C1C,-C1E,-C1F,-C2A,-C2C,-C2E,-D2A,-F1A6; LO-360-A1G6D; TO-360-C1A6D	Wide	Aug. 1981	PC-306-2A	June 1986	30.00

♦ - Reprinted

● - Photocopy

Part Number	Engine Application	Cyl. Flange	Current Edition	Revision Number*	Revision Date	List Price
PC-306-3	O-360-A4N	Wide	Oct. 1982			\$15.00
PC-306-4	O-360-C1G	Wide	Feb. 1987	PC-306-4A	Mar. 1994	15.00
PC-306-5	O, LO-360-A1H6	Wide	Nov. 1989			15.00
PC-306-6	O-360-A1P	Wide	March 1994			15.00
PC-306-7	O-360-B2C	Wide	Sept. 1994			15.00
PC-306-8	O-360-C4F,-C4P	Wide	Oct. 1995			15.00
PC-306-9	O-360-A4P	Wide	Nov. 1995			15.00
PC-306-10	HO-360-C1A	Wide	March 1996			15.00
PC-306-11	O-360-J2A	Wide	Jan. 1996	PC-306-11A	Sept. 1998	15.00
PC-306-12	IO-360-L2A	Wide	May 1996	PC-306-12A	Sept. 1998	15.00
PC-306-13	IO-360-B1G6	Wide	June 1999			15.00
PC-306-14	IO-360-M1A	Wide	Jan. 2000	PC-306-14A	Oct. 2000	15.00
PC-306-15	IO-360-C1G6	Wide	Nov. 2005			30.00
PC-306-16	IO-360-M1B	Wide	Dec. 2005			30.00
PC-315-1♦	TIO, LTIO-540-U2A	Wide	Feb. 1983	PC-315-1A	Feb. 1995	15.00
PC-315-2	TIO, LTIO-540-V2AD	Wide	Dec. 1983	PC-315-2A	July 1986	15.00
PC-315-3	TIO-540-AB1AD	Wide	May 1985			15.00
PC-315-4	TIO-540-AA1AD	Wide	Jan. 1987			15.00
PC-315-5	TIO-540-A2B,-A2C,-C1A,-F2BD, -J2B,-J2BD,-N2BD,-R2AD,-S1AD; LTIO-540-F2BD,-J2B,-J2BD, -N2BD,-R2AD	Wide	Oct. 1991	PC-315-5A SSP493 PC-315-5B PC-315-5C	Oct. 1992 June 1993 Feb. 1995 Dec. 1996	35.00
PC-315-6	TIO-540-A1A,-A1B,-A2A,-A2B, -A2C,-C1A,-E1A,-G1A,-H1A	Std.	Oct. 1991	PC-315-6A	Oct. 1992	35.00
PC-315-7	TIO-540-AE2A	Wide	March 1989	PC-315-7A PC-315-7B	Feb. 1995 Dec. 1996	15.00
PC-315-8	TIO-540-AF1A, -AF1B	Wide	Sept. 1989	PC-315-8A PC-315-8B	Feb. 1995 Nov. 2002	15.00
PC-315-9	TIO-540-AG1A	Wide	Sept. 1995			15.00
PC-315-10	TIO-540-AH1A	Wide	July 1998			15.00
PC-315-11	TIO-540-W2A	Wide	Jan. 1999			15.00
PC-315-12	TIO-540-AJ1A	Wide	May 1999			20.00
PC-315-13	TIO-540-AK1A	Wide	Aug. 2001	PC-315-13A	Aug. 2001	20.00
PC-406-1	IO-360-A1A,-A1B,-A1B6,-A1B6D, -A1C,-A1D,-A1D6,-A2A,-A2B, -A3B6D,-B1B,-B1D,-B1E,-B1F, -B2F,-B2F6,-B4A; AIO-360-A1A, -A1B,-B1B	Wide	April 1991	SSP291 SSP295 PC-406-1A PC-406-1B PC-406-1C	April 1991 Feb. 1995 Oct. 1995 Nov. 1995 Dec. 1996	35.00

♦ - Reprinted.

● - Photocopy

Part Number	Engine Application	Cyl. Flange	Current Edition	Revision Number*	Revision Date	List Price
PC-406-2	IO-360-C1A,-C1B,-C1C,-C1C6, -C1D6,-C1E6,-C1F,-J1A6D; LIO-360-C1E6; HIO-360-A1A,-B1A, -C1A,-C1B,-D1A,-E1AD,-E1BD, -F1AD; TIO-360-A1B; AEIO-360- A1E,-B1G6,-H1A	Wide	April 1983	PC-406-2A PC-406-2B	Nov. 1984 Mar. 1986	\$35.00
PC-406-3	TIO-360-C1A6D	Wide	March 1986	PC-406-3A	Dec. 1996	15.00
PC-406-4	AEIO-360-B1B, -B1F, -B1H	Wide	Dec. 2005			30.00
PC-406-5	AEIO-360-H1B	Wide	Sept. 2003			15.00
PC-406-6	HIO-360-G1A	Wide	Feb. 2003			15.00
PC-415-1	O-540-J1A5D,-J3A5,-J3A5D, -J3C5D,-L3C5D	Wide	March 1994			35.00
PC-515	O-540-B2B5,-B2C5,-B4B5,-E4A5, -E4B5,-E4C5,-G1A5,-H1B5D, -H2B5D	Wide	Dec. 1978	PC-515-1	Mar. 1979	35.00
PC-515-2	O-540-F1B5	Wide	Aug. 1993	PC-515-2A	Sept. 1998	15.00
PC-515-3	O-540-A4D5	Wide	Feb. 2003			15.00
PC-515-4	O-540-H2A5	Wide	Nov. 2005			30.00
PC-615	IO-540-C4B5,-D4A5,-G1D5,-K1A5, -K1A5D,-K1B5,-K1D5,-K1E5, -K1F5,-K1F5D,-K1G5,-K1G5D, -K1J5, -K1J5D,-S1A5,-T4A5D, -T4B5D	Wide	Oct., 1979	SSP1080 SSP881 SSP1084-1 SSP290 SSP192	Nov. 1980 Aug. 1981 Jan. 1985 April 1990 Jan. 1992	35.00
PC-615-1	IO-540-C4D5D	Wide	July 1982			15.00
PC-615-2	IO-540-K1K5, -K1H5	Wide	Nov. 1983	PC-615-2A PC-615-2B PC-615-2C	June 1985 Feb. 2003 Feb. 2003	15.00
PC-615-3	IO-540-V4A5D	Wide	Dec. 1984	PC-615-3A	June 2001	15.00
PC-615-4	IO-540-W Series	Wide	Oct. 1993			35.00
PC-615-5	IO-540-L1C5	Wide	July 1986			15.00
PC-615-7	AEIO-540-L1B5D	Wide	March 1987			15.00
PC-615-8	IO-540-T Series (-T4A5D,-T4B5, -T4B5D,-T4C5D)	Wide	Oct. 1992			35.00
PC-615-9	AEIO-540-L1B5	Wide	Dec. 1989			15.00
PC-615-10	IO-540-AB1A5	Wide	April 1997	PC-615-10A	Sept. 1998	15.00
PC-615-11	AEIO-540-D4A5,-D4B5	Wide	Oct. 1991	PC-615-11A	Sept. 2001	15.00
PC-615-12	IO-540-AC1A5	Wide	Feb. 1999			15.00
PC-615-13	IO-540-AE1A5	Wide	Jan. 2003			25.00
PC-701-1	IO-580-B1A	Wide	March 2003			30.00
Binders.....						8.00

◆ - Reprinted

● - Photocopy

***PARTS CATALOG REVISIONS** – Parts catalog revisions may be purchased for a list price of \$10.00 each. Complete engine model information must be supplied when ordering.

SERVICE BULLETINS, INSTRUCTIONS, LETTERS – These publications are issued as required. Service Bulletins are mandatory and require some modification or inspection to be accomplished on the engine within a specified time. Service Instructions cover a variety of subjects; such as repair processes, modification procedures, inspection procedures and overhaul methods. Service Letters usually pertain to service policy or vendor products. The latest index of these publications is available as listed under SPECIAL SERVICE PUBLICATIONS.

NOTE: Customers that have purchased complete sets of active bulletins, letters and instructions including subscription will receive notice when their subscription is due for renewal.

Part Number	Description	Net Price
BS-145	Domestic Subscription	\$35.00
BS-146	International Subscription (Export, Canada, Mexico)	\$50.00
BS-147*	Complete set of active bulletins, letters and instructions (Domestic)	\$120.00
BS-150*	Complete set of active bulletins, letters and instructions (Export, Canada, Mexico)	\$140.00
BS-148*	Complete set of active bulletins, letters and instructions including one year subscription (Domestic)	\$140.00
BS-149*	Complete set of active bulletins, letters and instructions including one year subscription (Export, Canada, Mexico)	\$165.00

* - Includes Index.

CD-ROM PUBLICATIONS –

Part Number	Title	List Price
*BD3	4 Cylinder Maintenance Library	\$399.00
*BD2	6 and 8 Cylinder Maintenance Library	\$399.00
*BEX	Lycoming Service Information Library	\$299.00
*BD6	Complete Lycoming Maintenance Library	\$649.00
*CD-ROM	Complete Set of Active Service Bulletins, Letters and Instructions, Including One-Year Subscription – Note 1	\$299.00
CD-4 Cyl-S	Single CD – 4 Cylinder Engines with Annual Subscription – Note 2	\$349.00
CD-6 Cyl-S	Single CD – 6 Cylinder Engines with Annual Subscription – Note 2	\$349.00
CD-4 & 6 Cyl.-S	Single CD – 4 & 6 Cylinder Engines with Annual Subscription – Note 2	\$499.00
CD-8 Cyl-S	Single CD – 8 Cylinder Engines with Annual Subscription – Note 2	\$349.00
CD-Heli-S	Single CD – Helicopter Engines with Annual Subscription – Note 2	\$349.00
CD-Aero-S	Single CD – Aerobatic Engines with Annual Subscription – Note 2	\$349.00
CD-Library-S	Complete Set with Annual Subscription – Note 2	\$649.00
CD-IO-360	IO-360 Training Guide	\$249.00

* - Purchase of these CD's requires a signed licensed agreement with ATP.

NOTE 1 – Includes one-year subscription which provides an updated CD every 8 weeks.

NOTE 2 – Contains Operator's Manuals, Overhaul Manuals, Parts Catalogs, Special Publications (Bulletins, Letters, and Instructions) and Price Lists. Annual subscriptions provide updated CD's quarterly. For international shipments, add \$70.00 shipping/handling.

MICROFICHE PUBLICATIONS – These publications are available for purchase on microfiche: Service Bulletins, Instructions, and Letters, Overhaul Manuals, and Parts Catalogs. Refer to Service Letter No. L230 for the most current listing and pricing.

SPECIAL SERVICE PUBLICATIONS – These publications are concerned with topics of general interest or subjects that are too lengthy for inclusion in maintenance manuals.

Part Number	Title	Publication Date	List Price
SSP-3867	Schematic – Turbocharger Control System (TVO-435-A1A)		\$10.00
SSP-3967	Schematic – Turbocharger Control System (TIO-541-A)		10.00
SSP-1668-1	Schematic – Turbocharger Control System (TIO-540-A Series)		10.00
SSP-669	Schematic – Turbocharger Control System (TIO-540-C1A)		10.00

SPECIAL SERVICE PUBLICATIONS (CONT.):

Part Number	Title	Publication Date	List Price
SSP-669	Schematic – Turbocharger Control System (TIO-540-C1A)		10.00
SSP-1169	Engine Test Equipment		10.00
SSP-1670-1	Schematic – RSA-10DB2 Fuel Injector System		10.00
SSP-871	TIO-360 Turbocharger System Chart		10.00
SSP-1272	Schematic – TIO-540-J2BD		10.00
SSP-1872	Engine Log Book		N/C
SSP-973	Schematic – RSA-5 and RSA-10 Fuel Injector System		10.00
SSP-1173	Schematic RS-10B1 Fuel System		10.00
SSP-475	Trouble-Shooting Manual	1977	\$10.00
SSP-1776	Table of Limits, Complete Book		50.00
SSP-1776-PT1*	Table of Limits, Part I Direct Drive Only	April 1979	20.00
SSP-1776-PT2*	Table of Limits, Part II Integral Only	July 1979	20.00
SSP-1776-PT3*	Table of Limits, Part III Geared Only	Jan. 1980	20.00
SSP-1776-PT4*	Table of Limits, Part IV Vertical Only	Feb. 1980	20.00
SSP-479	Schematic – Turbocharger Control System (TIO, TIGO-541-E, TIO-540-R)		10.00
SSP-384	Special Service Tools	Jan. 1985	10.00
SSP-885-2	Oil Filter Replacement Kits	Feb. 2003	10.00
SSP-204	Certificated Engine List	Feb. 2004	10.00
SSP-490	Component Maintenance Manual (Lycoming Lightweight Starter)	Jan. 1991	15.00
SSP-303	Index of Service Bulletins, Letters and Instructions	Aug. 2003	10.00
SSP-499B	Numerical Parts History	June 2003	15.00
Form SFN-880-3	Cylinder, Piston, Piston Ring and Gasket Set Application List	March 2000	15.00

* - These publications are sent with Overhaul Manuals. Direct Drive and 76 Series Overhaul Manual owners get Part I, Integral Overhaul Manual owners get Part II, etc.

ATTENTION:**OWNERS AND OPERATORS OF TEXTRON LYCOMING ENGINES**

To reduce exposure to legal action, which is highly probable due to the present product liability crisis, Lycoming can no longer resell/distribute any vendor publication.

Vendor publications can be obtained directly from the vendor. Current vendor addresses are listed on pages 7, 8 and 9 of this Service Letter.

Further, all Lycoming publications are to be considered copyrighted and may not be reproduced without permission of the company.

VENDOR ADDRESSES**ALTERNATOR**

■ KELLY AEROSPACE POWER SYSTEMS, INC.
 Airport Complex
 P.O. Box 273
 Fort Deposit, AL 36032
 Phone: (334) 227-8306
 Fax: (334) 227-8596
■ Web Site: www.kellyaerospace.com

STARTER

■ KELLY AEROSPACE POWER SYSTEMS, INC.
 Airport Complex
 P.O. Box 273
 Fort Deposit, AL 36032
 Phone: (334) 227-8306
 Fax: (334) 227-8596
■ Web Site: www.kellyaerospace.com

VENDOR ADDRESSES (CONT.):

STARTER (CONT.)

SKY-TEC
350 Howard Clemmons Road
Granbury, TX 76048
Phone: 1-800-476-7896
Fax: (817) 573-2252
Web Site: www.skytechair.com

LAMAR TECHNOLOGIES
14800 40th Ave. N.E.
Marysville, WA 98271
Phone: (360) 651-6666
Fax: (360) 651-6677
Web Site: www.larmartech.com

CARBURETOR

PRECISION AIRMOTIVE
14800 40th Ave. N.E.
Marysville, WA 98271
Phone: (360) 651-8282
Fax: (360) 651-8080
Web Site: www.precisionairmotive.com

CARBURETOR, PRESSURE

PRECISION AIRMOTIVE
14800 40th Ave. N.E.
Marysville, WA 98271
Phone: (360) 651-8282
Fax: (360) 651-8080
Web Site: www.precisionairmotive.com

FUEL PUMP

CRANE LEAR ROMEC
241 South Abbe Road
Elyria, OH 44035
Phone: (440) 343-3211
Fax: (440) 322-2278
Web Site: www.learromec.com

KELLY AEROSPACE POWER SYSTEMS, INC.
1400 East South Blvd.
Montgomery, AL 36116-2320
Phone: (334) 286-8551
Fax: (334) 286-8018
Web Site: www.kellyaerospace.com

FUEL INJECTOR

PRECISION AIRMOTIVE
14800 40th Ave. N.E.
Marysville, WA 98271
Phone: (360) 651-8282
Fax: (360) 651-8080
Web Site: www.precisionairmotive.com

MAGNETO, BENDIX

TELEDYNE CONTINENTAL MOTORS
Aircraft Products Division
P.O. Box 90
Mobile, AL 36601
Phone: (251) 438-3411
Fax: (251) 432-7352

VENDOR ADDRESSES (CONT.)

MAGNETO, SLICK

UNISON INDUSTRIES
SLICK AIRCRAFT PRODUCTS
550 Blackhawk Park Avenue
Rockford, IL 61104
Attn: Publications Dept.
Phone: (815) 965-4700
Fax: (815) 965-2457

TURBOCHARGER CONTROLLER

KELLY AEROSPACE POWER SYSTEMS, INC.
1400 East South Blvd.
Montgomery, AL 36116-2320
Phone: (334) 286-8551
Fax: (334) 286-8018
Web Site: www.kellyaerospace.com

CHRISTEN AEROBATIC SYSTEM

AVIAT, INC.
P.O. Box 1149
Afton, WY 83110
Phone: (307) 886-3151
Fax: (307) 886-9674

NOTE

**LYCOMING WILL NO LONGER SUPPLY AIRESEARCH OVERHAUL MANUALS,
MAINTENANCE MANUALS AND PARTS CATALOGS.**

LYCOMING ENGINES
DOMESTIC PUBLICATIONS ORDER FORM



652 Oliver Street
Williamsport, PA 17701 U.S.A.
Attention: Publications

PHONE ORDERS (570)-327-7274

FAX ORDERS (570) 327-7275 - Credit Card Only

Printed publications are not returnable; CD's may be returned within 15 days if unopened.

Part No.	Description	Qty.	Unit Price	Total Price

* All orders are F.O.B. Shipping Point. Shipping and handling charges will be added to invoice. No P.O. Box # for overnight delivery.

PAYMENT

Do not send cash.



- ☐ Check Enclosed
- ☐ Money Order
- ☐ Master Card
- ☐ VISA
- ☐ American Express

Account No. _____

Exp. Date _____

Name on Card _____

Signature

SUBTOTAL	
*SHIPPING AND HANDLING:	
\$0-\$20 \$5.00	
\$21-\$50 \$10.00	
\$51& UP \$15.00	
Overnight Service Add \$15.00	
SUBTOTAL OF ORDER	
PA residents add 6% sales tax	
TOTAL ORDER	

PLEASE TYPE OR PRINT

Name _____

Company _____

Street _____

City _____ State _____ Zip _____

Phone () _____ Fax () _____

e-mail _____

LYCOMING ENGINES
EXPORT PUBLICATIONS ORDER FORM



652 Oliver Street
Williamsport, PA 17701 U.S.A.
Attention: Publications

PHONE ORDERS - (570) 327-7274 OR FAX ORDERS Credit Card Only - (570) 327-7275

Printed publications are not returnable; CD's may be returned within 15 days if unopened.

Part No.	Description	Qty.	Unit Price	Total Price

* All orders are F.O.B. Shipping Point. Shipping and handling charges will be added to invoice.

PAYMENT

Do not send cash. ☐ Check Enclosed

☐ Money Order

☐ Master Card

☐ VISA

☐ American Express



SUBTOTAL

***SHIPPING AND HANDLING:**

\$0-\$50 \$30.00

\$51-\$100 \$45.00

\$101 & UP \$60.00

Account No. _____

Exp. Date _____

Name on Card _____

TOTAL ORDER

Signature _____

If paying by wire transfer, please allow \$25.00 for banking charges.

REMIT TO: Textron Lycoming
via S.W.I.F.T. system to:

The Chase Manhattan Bank N.A. Chas US 33
Textron Lycoming Account #910-2-554798
4 Chase Metrotech Center
Brooklyn NY 11245

PAYMENT IN US DOLLARS ONLY - CHECKS MUST BE DRAWN ON U.S. BANK
PLEASE TYPE OR PRINT

Name _____

Company _____

Street _____

City _____ State _____ Zip _____

Country _____

Phone () _____ Fax () _____ e-mail _____